

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/001		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 001	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE  LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022 18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, of or any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/002.		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 002	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE  LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022 18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, of or any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/003		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 003	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE  LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, of or any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/004		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 004	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE  LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022 18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, of or any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							



# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/005		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 005	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE  LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, of or any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/006		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 006	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE  LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, of or any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/007		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 007	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE  LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022 18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, of or any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/008		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 008	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE  LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, of or any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							



# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/009		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 009	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE  LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022 18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, of or any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/010		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 010	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE  LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, of or any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/011		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 011	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE  LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022 18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEE, LIFTING GEAR GENERAL ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, of or any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/012		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 012	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE  LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEE, LIFTING GEAR GENERAL ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, of or any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							



# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/013		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 013	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE  LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022 18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEE, LIFTING GEAR GENERAL ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, of or any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/014		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 014	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE  LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, of or any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/015		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 015	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE  LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022 18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, of or any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/016		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 016	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE  LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, of or any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							



# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/017		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 017	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE  LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEE, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, of or any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/018		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 018	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE  LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEE, LIFTING GEAR GENERAL ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, of or any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/019		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 019	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE  LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, of or any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/020		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 020	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE  LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEE, LIFTING GEAR GENERAL ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, of or any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							



# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/021		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 021	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE  LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022 18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, of or any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/022		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 022	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE  LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEE, LIFTING GEAR GENERAL ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, of or any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/023		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 023	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE  LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, of or any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/024		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 024	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE  LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, of or any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							



# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/025		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 025	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE  LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022 18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, of or any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/026		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 026	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE  LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEE, LIFTING GEAR GENERAL ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, of or any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/027		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 027	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE  LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, of or any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/028		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 028	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE  LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, of or any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							



# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/029		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 029	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE   LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEE, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, of or any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/030		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 030	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE  LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, of or any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/031		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 031	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE   LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEE, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, of or any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/032		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 032	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE  LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, of or any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							



# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/033		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 033	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE  LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, of or any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/034		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 034	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE   LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, of or any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/035		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 035	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE  LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, of or any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/036		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 036	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE   LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							



# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/037		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 037	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE   LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEE, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/038		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 038	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE   LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEE, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/039		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 039	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE       LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEE, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/040		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 040	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE  LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							



# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/041		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 041	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE   LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/042		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 042	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE   LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/043		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 043	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE  LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEE, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/045		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 045	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE        LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEE, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							



# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/046		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 046	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE   LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/047		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 047	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE   LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/048		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 048	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE   LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEE, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/049		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 049	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE   LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							



# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/050		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 050	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE   LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEE, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/051		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 051	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE   LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEE, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/052		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 052	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE   LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEE, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/053		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 053	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE   LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Failed		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> N/A		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							



# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/054		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 054	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE  LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/055		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 055	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE   LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/056		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 056	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE   LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/057		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 057	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE   LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Failed		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> N/A		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							



# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/058		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 058	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE  LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEE, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/059		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 059	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE   LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEE, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/060		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 060	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE   LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/061		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 061	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE  LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							



# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/062		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 062	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE   LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/062		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 062	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE   LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEE, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/063		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 063	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE   LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEE, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/064		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 064	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE   LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							



# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/064		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 064	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE   LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEE, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/065		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 065	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE   LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/066		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 066	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE   LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEE, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/067		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 067	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE  LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							



# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/068		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 068	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE  LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/069		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 069	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE   LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEE, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/070		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 071	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE   LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/072		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 072	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE   LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							



# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/073			<b>Office:</b> Colombo			<b>Date:</b> 19/08/2022	
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka					<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable		
<b>(1) PARTICULARS</b>					<b>Customer Order No.</b>		
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 073	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE   LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEE, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/074		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 074	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE   LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/075		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 075	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE   LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/076		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 076	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE   LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEE, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							



# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/077		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 077	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE   LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/078		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 078	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE   LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEE, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/079		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 079	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE   LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/080		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 080	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE   LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							



# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/081		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 081	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE   LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEE, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/082		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 082	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE   LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEE, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/083		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 083	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE   LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/084		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 084	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE   LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							



# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/085		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 085	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE       LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/086		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 086	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE   LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEE, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/087		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 087	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE   LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/088		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 088	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE   LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEE, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							



# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/089		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 089	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE   LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/090		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 090	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE   LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/091		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 091	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE   LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEE, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/092		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 092	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE   LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEE, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							



# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/093		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 093	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE   LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEE, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/094			<b>Office:</b> Colombo			<b>Date:</b> 19/08/2022	
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka					<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable		
<b>(1) PARTICULARS</b>					<b>Customer Order No.</b>		
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase  (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 094	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE  LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEEA, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							

# HEIGHTSWORK PVT LTD.

## TEST & THOROUGH EXAMINATION CERTIFICATE

<b>Certificate No.</b> DB/22-09-100/095		<b>Office:</b> Colombo		<b>Date:</b> 19/08/2022			
<b>Invoice Address:</b> Sampath Centre Limited. NO 110, Sir James Peiris Mawatha, Colombo 02. Sri Lanka				<b>Site Name:</b> Sampath Centre  <b>Site Location:</b> Colombo - 02  <b>Site Colour Code:</b> Not Applicable			
<b>(1) PARTICULARS</b>				<b>Customer Order No.</b>			
Unique Serial Number  (i)	Batch Number and Model No  (ii)	Description of item. This should include size, material and particulars of any heat treatment  (iii)	Quantity  (iv)	Date of Examination  Date of Purchase (v)	Proof Load (specify units)  (vi)	Safe Working Load (specify units)  (vi)	Manufacturing Date  (viii)
S/N: 095	N/A	REMOVABLE STAINLESS-STEEL COEUR ANCHORAGE LIFTING LUG SIZE 12MM BOLT HOLE   LOCATION: PLEASE REFER TO LOCATOR DRAWINGS	1	18/08/2022  18/09/2020	7.5 kN	6 kN	Unknown
<b>Tested in accordance with:</b> API RP 2A WSD 2000 & EN 795					<b>Result:</b> Satisfactory		
(2)	<b>Name and address of Maker, Supplier or Repairer.</b>				PETZL, UNITED KINGDOM		
(3)	<b>Name and address of firm, company, association or person undertaking the test and examination.</b>				HEIGHTSWORK PVT LTD. No.:11, HILCREST HOUSING SCHEME, NIUNGAMA, PILIYANDALA, SRI LANKA.		
(4)	<b>Name, position and qualification of person who carried out the test and examination.</b>				DON BUDDHIKA LEE, LIFTING GEAR GENERAL. ASNT LEVEL II UT, MT, ET, VT, PT. IRATA LEVEL 2 -2/160179 LIFTING GEAR INSPECTOR		
(5)	<b>Equipment Location.</b>				ROOFTOP		
(6)	<b>I certify on behalf of the firm, company, association or person named in (3) and (4) above that the items described herein were tested and thereafter examined and were found to be free from cracks, flaws or other defects.</b>						
<b>Signature</b>		<b>Countersigned</b>			<b>Valid Until:</b> 18/08/2023		
<small>           This certification or report is granted or issued subject to the condition that it is understood and agreed upon that nothing herein shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer, or operator of any warranty, express or implied and HEIGHTSWORK. Liability shall be limited to the acts and omissions of its employees, agents, and subcontractors. Under no circumstances shall HEIGHTSWORK be liable for any injury or damage to any person or property occurring by reason of negligent operation, misuse, or of any defect in materials, machinery, equipment, or other items other than by defects in items actually inspected by HEIGHTSWORK and ascertainable by normally accepted testing standards, or defects reflected in documents reviewed by HEIGHTSWORK and which are covered by this certificate or report.            The certificate or report and the recommendations contained in it are based upon the conditions and practices observed and information made available to HEIGHTSWORK personnel. The report does not purport to list all hazards or faulty conditions not to indicate that other hazards or faulty conditions exist. Severity ratings in the report are based on the criteria shown in this report and are intended as guidelines only. No responsibility is assumed for the control or correction of conditions.         </small>							
<small>           HEIGHTSWORK (Pvt) Ltd. No.:11, Hilcrest Housing Scheme, Niungama, Piliyandala, Tel: +94 115 968666            Website: www.heightswork.com         </small>							